

Major Repairs	Building	Status
Re-roofing	Iliahi (Subway side) Kaulia A&B Koa A & B Kokio Kalia Kopiko Ohia Ohelo Olonā [ID not correct as of May 2011?]	in process 2011 completed 2011 in process 2011 completed 2010 completed 2011 completed 2007 completed design phase in 2010
Air-conditioning	Naio Iliahi Kalia Kopiko Lama Manele Manono Naio Ohelo Ohia Olapa Olonā [ID not correct?]	completed 2007 all systems completed - 2011 completed 2007 included exchange of jalousie windows for sealed ones, replacement of first floor ducts and ceiling, installation of a reheat feature in to air conditioning system to control humidity and abate moisture completed 2007 completed 2007
Repair/resurface asphalt walkways/ bike path/ other walkways	campuswide	

Electrical Infrastructure Assessment and Energy Saving Performance Contract (system wide) and upgrade electrical systems (campus wide)		
Upgrade restrooms:	Kokio	
	Ilima	
	Iliahi	
	Kaulia	
Repair & refurbish exterior lighting	(campus wide)	
Foliage management		